

This Page Is Inserted by IFW Operations
and is not a part of the Official Record

BEST AVAILABLE IMAGES

Defective images within this document are accurate representations of the original documents submitted by the applicant.

Defects in the images may include (but are not limited to):

- BLACK BORDERS
- TEXT CUT OFF AT TOP, BOTTOM OR SIDES
- FADED TEXT
- ILLEGIBLE TEXT
- SKEWED/SLANTED IMAGES
- COLORED PHOTOS
- BLACK OR VERY BLACK AND WHITE DARK PHOTOS
- GRAY SCALE DOCUMENTS

IMAGES ARE BEST AVAILABLE COPY.

**As rescanning documents *will not* correct images,
please do not report the images to the
Image Problem Mailbox.**

In the Specification:

Please replace the paragraph beginning on page 2, line 9, with the following rewritten paragraph:

In certain situations, additional portions of the tibia, other than the relatively narrow proximal portion being removed during knee replacement surgery, may also be damaged by arthritis or other problems. In such situations, a relatively thick proximal portion of the tibia is often removed, and it is replaced with an augment block shaped like the bone that has been removed. However, such previously known methods often result in the removal of an unnecessary amount of healthy bone, along with the damaged bone. Thus, for example, even in cases where the peripheral bone was healthy, and only the internal bone was damaged, prior art methods often removed both the healthy peripheral bone and the damaged internal ~~bone~~ bone.